

PROCEEDINGS OF THE INTERNATIONAL SYMPOSIUM ON GEOTECHNICAL
ENGINEERING FOR THE PRESERVATION OF MONUMENTS AND HISTORIC SITES
NAPOLI/ITALY/3-4 OCTOBER 1996

GEOTECHNICAL ENGINEERING FOR THE PRESERVATION OF MONUMENTS AND HISTORIC SITES

Edited by

CARLO VIGGIANI

University of Napoli Federico II, Italy



A.A.BALKEMA/ROTTERDAM/BROOKFIELD/1997

The texts of the various papers in this volume were set individually by typists under the supervision of each of the authors concerned.

Authorization to photocopy items for internal or personal use, or the internal or personal use of specific clients, is granted by A.A. Balkema, Rotterdam, provided that the base fee of US\$1.50 per copy, plus US\$0.10 per page is paid directly to Copyright Clearance Center, 222 Rosewood Drive, Danvers, MA 01923, USA. For those organizations that have been granted a photocopy license by CCC, a separate system of payment has been arranged. The fee code for users of the Transactional Reporting Service is: 90 5410 871 1/97 US\$1.50 + US\$0.10.

Published by


A.A. Balkema, P.O. Box 1675, 3000 BR Rotterdam, Netherlands (Fax: +31.10.413.5947)

A.A. Balkema Publishers, Old Post Road, Brookfield, VT 05036-9704, USA (Fax: 802.276.3837)

ISBN 90 5410 871 1

© 1997 A.A. Balkema, Rotterdam

Printed in the Netherlands



In Honor of
Arrigo Croce
1914-1994

Table of contents

Preface	XV
Organisation	XVII
<i>Introduction</i>	
Opening address <i>C.Viggiani</i>	3
An integrated approach to the safeguard of monuments: The contribution of Arrigo Croce <i>R.Jappelli</i>	11
Laudatio <i>C.Viggiani</i>	29
Geotechnical problems in the Egypt of Pharaohs <i>J.Kerisel</i>	33
<i>Investigations</i>	
General report for session 2: Investigations <i>U.Smolczyk</i>	43
Stability of the vertical cliff overhanging Via Krupp in Capri <i>S.Aversa, M.Candela, N.Nocilla & G.Urciuoli</i>	49
Studies of materials and foundation of Peruvian prehispanic monuments <i>A.Carrillo Gil</i>	61
Comparative analysis of some Italian monuments <i>M.Cecconi, P.Croce & M.G.D'Amelio</i>	69
On the role played by settlements in the statics of masonry monuments <i>M.Como</i>	81
The geotechnical settlements of the archaeological site of Sibari <i>M.R.Coop & F.Cotecchia</i>	89
Geotechnical degradation of the archaeological site of Agrigento <i>V.Cotecchia</i>	101

The geolithological and geomechanical characteristics of Agrigento calcarenites <i>V.Cotecchia, C.Cherubini, L.Cucchiararo, F.P.Ramunni & R.Pagliarulo</i>	109
Geotechnical problems and lessons from engineering works in the historic centre of Cagliari <i>T.Crespellani & L.Fenu</i>	119
Seismic risk assessment for the preservation of historical buildings in the city of Gubbio <i>T.Crespellani & C.A.Garzonio</i>	129
Studies aimed to the consolidation of the cliff where the middleage Corniglio town is built <i>C.Deangeli, A.Segalini & G.P.Giani</i>	139
The impact of swell properties of the Esna-Shale on ancient monuments of the Deir El-Bahari <i>A.F.El-Banna & J.Pinińska</i>	145
Historical hollows in Central Germany – Geotechnical problems <i>J.Engel & D.Franke</i>	157
Stability problems of old towns built on relict <i>plateaux</i> resting on clay deposits <i>G.B.Fenelli, A.Pellegrino & L.Picarelli</i>	163
Stability analysis of ancient monuments by tridimensional numerical models <i>G.P.Giani & A.M.Ferrero</i>	175
Application of geophysical methods in structural historical investigation in the Czech Republic <i>V.Hásek & V.Glisníková</i>	185
Recommendations and prejudices in the realm of foundation engineering in Italy: A historical review <i>R.Jappelli & N.Marconi</i>	191
Determination of the lengths of old timber piles by the Hammer-Blow method <i>M.Ladjarevic & M.Goldscheider</i>	215
Seismic response analysis of historical buildings <i>M.Maugeri, G.Muscolino & G.Pracanica</i>	225
Review of some historic sites in Argentina <i>C.A.Micucci</i>	239
Survey and preservation of the wooden heritage <i>T.A.Nazarova</i>	247
Bending of Dionysos marble architrave <i>D.N.Pazis, N.P.Andrianopoulos, I.Vardoulakis & S.K.Kourkoulis</i>	251
A description of pyroclastic soils that buried Pompeii and Herculaneum in A.D. 79 <i>F.Rippa</i>	261
Geotechnical micro-zoning of Ston with special emphasis on the old city core <i>T.Roje-Bonacci</i>	271
Experimental techniques for the structural analysis of historical buildings <i>P.P.Rossi</i>	275

Geotechnical investigation for the preservation of Chania Venetian Fortress site, Crete, Greece <i>D.Rozos & N.Nikolaou</i>	287
History and geotechnics of the Domus Tiberii on the Palatine Hill in Rome <i>G.Scarpelli, E.Sakellariadi & M.Cittadini</i>	293
Compression phenomena responsible for the current ground level in the town of Aquileia (NE Italy) <i>M.Soranzo</i>	305
Geotechnical prognosis for the reconstruction purposes <i>V.Ulitzky & A.Shashkin</i>	313
<i>Monitoring</i>	
Geotechnical monitoring of historic monuments <i>J.B.Burland & J.R.Standing</i>	321
Monitoring of Castel dell'Ovo in Napoli – Preliminary results <i>M.Candela, A.Mandolini & G.Russo</i>	343
Monitoring of the installation of piles beneath the Round Tower, Windsor Castle, UK <i>F.R.D.Chartres</i>	349
Behavior of a building in Venice during and after underpinning <i>F.Colleselli & G.Cortellazzo</i>	357
Geotechnical studies and measurements on castles in Eastern Germany <i>G.Heise, R.Thiele & D.Tonderra</i>	365
Monitoring system of St. Mark's Basilica in Venice: Analysis and interpretation of the data <i>C.Rossi, P.P.Rossi & E.Vio</i>	373
Testing and monitoring for the restoration of the Metropolitan Cathedral in Mexico City <i>P.P.Rossi & S.Zaldivar Guerra</i>	387
Crack monitoring using a demountable mechanical strain gauge <i>G.Viggiani & J.R.Standing</i>	397
<i>Intervention techniques</i>	
Monuments and historic sites: Intervention techniques <i>G.Calabresi & S.D'Agostino</i>	409
EUROBOR – Venezia care: Highlights of the in situ preservation of wooden foundation <i>C.Birck & A.Jerbo</i>	427
Preservation problems in historical and artistic monuments of Venice <i>P.Colombo & F.Colleselli</i>	435
An integrated approach for preservation of heritage building in Egyptian practice <i>M.A.El-Sohby & M.F.Tarek</i>	445

Design of underpinning piles to control monument settlement <i>M.Georgiadis & C.Anagnostopoulos</i>	453
Preservation of historical monuments in Pakistan <i>Izhar-ul-Haq</i>	457
The Pali Radice (Micropiles) for the preservation of monuments and historic sites <i>F.Lizzi</i>	463
Preservation techniques for historical sites in Japan <i>K.Nishida & T.Nishigata</i>	471
Geotechnical aspects for underexcavating Mexico City's Metropolitan Cathedral: Main achievements after three years <i>E.Ovando-Shelley, E.Tamez González & E.Santoyo Villa</i>	479
The preservation of historical towns of Umbria: The Orvieto case and its observatory <i>V.Pane & E.Martini</i>	489
A review of recent Spanish interventions in monuments <i>J.M.Rodríguez Ortiz & P.R.Monteverde</i>	499
Recent experiences in Greece <i>A.C.Stamatopoulos</i>	509
 <i>Case histories</i>	
St-John's Church, Tartu, Estonia – Underpinning of tower <i>K.Avellan & K.Lange</i>	521
Conservation of the historic centre of Tricarico, Matera, Southern Italy <i>E.N.Bromhead, L.Coppola, T.Pescatore, H.M.Rendell & P.Toscano</i>	527
Rehabilitation of inner Paris sewer system <i>M.Bustamante, J.P.Gadret & D.Gouvenot</i>	535
Strengthening of a viaduct built at the beginning of the 20th century, by jet-grouting <i>M.Bustamante, L.Gianeselli & D.Thiriat</i>	543
Underpinning of the Bordeaux Pont-de-Pierre: A First Empire masonry bridge <i>M.Bustamante, L.Gianeselli & J.-L.Ledoux</i>	551
Reinforcement works of the calcareous rock under the Castle of Caccamo, Sicily <i>F.Cafiso & G.Umiltà</i>	561
Stabilization of a landslide involving the historic centre of Scarperia <i>C.Carrapetta, C.Madiai & G.Vannucchi</i>	571
Retrofitting of the Monastero SS.Salvatore in Noto, Sicily <i>F.Castelli, G.Gaeta, M.Maugeri & A.Pavone</i>	581
The preservation of historical towns of Umbria: The Todi case and its observatory <i>P.Conversini, V.Pane, G.Pialli & O.Fabrizi</i>	591

Classical F.E.M. analysis and experimental observations of the dome of the church of Givry, France <i>A.Coste & M.Boulon</i>	601
Strengthening measures for the foundations of Tilla Kari Mosque, Samarkand <i>G.Croci & V.M.Santoro</i>	609
Foundation underpinning of a tower of the Pilar Basilic in Zaragoza, Spain <i>P.De Porcellinis</i>	615
Settlement behaviour of a 17th century structure in Mexico City <i>J.Diaz Padilla</i>	621
Strengthening the castle tower in Vyborg <i>A.Fadeev, V.Inozemtcev & V.Lukin</i>	627
Settlement of a Gothic monastery in Prague <i>J.Feda & J.Boháč</i>	631
Subsoil characteristics and foundation settlement analysis of St. Mark's basilica in Venice <i>A.Gajo, M.Soranzo & R.Vitaliani</i>	637
Damages to masonry structures in the historical centres of Arezzo and Pistoia <i>A.Ghinelli & G.Vannucchi</i>	649
Strengthening of foundations in soft clay soils by embedded walls <i>L.K.Ginzburg, Ye.L.Korchagina, V.B.Shvets & N.S.Shvets</i>	655
Consolidation and restoration of the Medieval Castle of Laurenzana, Italy <i>A.Giuffré, C.Gambardella, G.Ciancia, R.Ciancia, M.Candela & D.Pingitore</i>	661
Stabilization of the foundations of the Castle of Schwerin using soft micro-piles <i>M.Goldscheider, S.Krieg & M.Ladjarevic</i>	667
History and preservation of the Nativity of our Suzdal Kremlin Lady Cathedral <i>V.Gulyaeva</i>	677
Damage and restoration of monuments in Olinda, Brazil <i>J.A.Gusmão Filho & G.De Brito Maia</i>	681
The stabilisation of the Dance School retaining wall, Coalbrookdale, near Ironbridge, Shropshire, England <i>E.Hull</i>	687
Geotechnical problem of Angkor monuments in Cambodia <i>Y.Iwasaki, M.Fukuda & T.Nakagawa</i>	697
Restoration of the historic complex of Reformed Franciscan Monastery in Wieliczka near Cracow <i>Z.Janowski & Z.Żmudziński</i>	705
Damage to the artistical patrimony in Piedmont due to the November 1994 flood <i>D.C.F.Lo Presti, A.Lazzari, V.Peisino & L.Vicentini</i>	713
Description of the restoration of an old building in the centre of Zagreb <i>B.Maric</i>	723

The 20th century renovation of the Great Ommayad Mosque in Damascus <i>F.S.Mawlawi</i>	729
Building rehabilitation in Madrid creating new basements: Fernando El Santo No. 15 <i>J.Monjo, J.Lacambra, J.Canalda, D.Fernandez & J.L.Fdez. Salso</i>	737
How to continue La Plata City Cathedral – Geotechnical approach <i>E.Nuñez & S.J.Trevisán</i>	745
Impact of regional subsidence and changing soil properties on the preservation of architectonic monuments in central Mexico City <i>E.Ovando-Shelley & V.Takahashi F.</i>	751
The coast in the area of the Herculaneum excavations at the time of the Romans <i>M.Pagano, T.Pescatore & F.Rippa</i>	759
Comprehensive geotechnical support for the construction of large edifices as part of St.Petersburg <i>N.A.Perminov</i>	767
‘Reichstag’-building, Berlin: Interaction between the historical and the new foundation <i>H.Quick, R.Katzenbach & U.Arslan</i>	773
Soil conditions in the site of the Three Hierarchies Church, Iași, Romania <i>P.Raileanu, V.Musat & T.Silion</i>	783
Geotechnical engineering for the preservation of San Vitale and Galla Placidia <i>G.Ricceri</i>	789
Stability appraisal and monitoring of a monumental piled tower <i>J.M.Rodríguez Ortiz</i>	799
Accidental settlements of buildings in Old Riga <i>Ju.Rossihin, Ja.Grabis & E.Tuzhilkin</i>	805
Building foundation conditions and slope stability of the national monuments La Alhambra and El Generalife <i>A.Santos, C.Oteo, J.M.Martínez & J.L.Salinas</i>	811
Civita di Bagnoregio: A town in decline <i>M.Sciotti, P.Focardi, C.Margottini, C.Ogliotti & S.Serafini</i>	819
Consolidation and restoration of the foundation and rock slope of Barbarossa Castle, Capri, Italy <i>A.Scott, A.Ambrosone, F.Rozza, M.T.Volpe, M.Cerullo & R.Filippini</i>	829
The impact of regional subsidence on the temple of Saint Augustine <i>J.Segovia, V.Hernandez & E.Ovando-Shelley</i>	835
Reconstruction of a cathedral placed on loess slump soils <i>K.Sh.Shadunts & V.V.Podtelkov</i>	845
Geotechnical aspects in the preservation of the historical town of Orvieto <i>P.Tommasi, R.Ribacchi & M.Sciotti</i>	849

The history of the brick neo-gothic Cathedral of La Plata City, Argentine <i>S.J.Trevisán & E.Nuñez</i>	859
Preservation of the Law Court along the Tiber in Rome <i>P.Ventura</i>	867
Underpinning of the historic building of J.Słowacki Theatre in Cracow <i>Z.Żmudziński & S.Karczmarczyk</i>	875
Author index	879