

PROCEEDINGS OF THE SECOND INTERNATIONAL SYMPOSIUM ON GEOTECHNICAL
ENGINEERING FOR THE PRESERVATION OF MONUMENTS AND HISTORIC SITES, NAPOLI,
ITALY, 30–31 MAY 2013

Geotechnical Engineering for the Preservation of Monuments and Historic Sites

Editors

Emilio Bilotta, Alessandro Flora, Stefania Lirer &
Carlo Viggiani

University of Naples Federico II, Napoli, Italy



CRC Press

Taylor & Francis Group

Boca Raton London New York Leiden

CRC Press is an imprint of the
Taylor & Francis Group, an **informa** business

A BALKEMA BOOK

CRC Press
Taylor & Francis Group
6000 Broken Sound Parkway NW, Suite 300
Boca Raton, FL 33487-2742

© 2013 by Taylor & Francis Group, LLC
CRC Press is an imprint of Taylor & Francis Group, an Informa business

No claim to original U.S. Government works
Version Date: 20130625

International Standard Book Number-13: 978-1-315-88749-4 (eBook - PDF)

This book contains information obtained from authentic and highly regarded sources. Reasonable efforts have been made to publish reliable data and information, but the author and publisher cannot assume responsibility for the validity of all materials or the consequences of their use. The authors and publishers have attempted to trace the copyright holders of all material reproduced in this publication and apologize to copyright holders if permission to publish in this form has not been obtained. If any copyright material has not been acknowledged please write and let us know so we may rectify in any future reprint.

Except as permitted under U.S. Copyright Law, no part of this book may be reprinted, reproduced, transmitted, or utilized in any form by any electronic, mechanical, or other means, now known or hereafter invented, including photocopying, microfilming, and recording, or in any information storage or retrieval system, without written permission from the publishers.

For permission to photocopy or use material electronically from this work, please access www.copyright.com (<http://www.copyright.com/>) or contact the Copyright Clearance Center, Inc. (CCC), 222 Rosewood Drive, Danvers, MA 01923, 978-750-8400. CCC is a not-for-profit organization that provides licenses and registration for a variety of users. For organizations that have been granted a photocopy license by the CCC, a separate system of payment has been arranged.

Trademark Notice: Product or corporate names may be trademarks or registered trademarks, and are used only for identification and explanation without intent to infringe.

Visit the Taylor & Francis Web site at
<http://www.taylorandfrancis.com>

and the CRC Press Web site at
<http://www.crcpress.com>

Table of contents

Preface	xi
Organization	xiii
 <i>Opening address</i>	
Cultural heritage and geotechnical engineering: An introduction <i>C. Viggiani</i>	3
 <i>Special lectures</i>	
Influence of the subsoil on the urban development of Napoli <i>S. Aversa, A. Evangelista & A. Scotto di Santolo</i>	15
Local site conditions and seismic risk assessment of historic buildings <i>D. D'Ayala & A. Ansal</i>	45
The role of monitoring and identification techniques on the preservation of historic towers <i>R. Lancellotta & D. Sabia</i>	57
Intervention techniques <i>E. Ovando-Shelley, E. Santoyo & M.O. Pinto de Oliveira</i>	75
 <i>Papers</i>	
New underground lines in historic centres: Experiences in Brescia <i>A.M. Ajmone Cat, E. Campa, M. Lodico & C. Umiliaco</i>	95
Safeguarding the historic town of San Fratello, Sicily <i>C. Airò Farulla & F. Cafiso</i>	105
Stability analysis of the underground masonry tunnel of Ancient Nemea <i>H. Alexakis & N. Makris</i>	113
Foundation systems of some heritage buildings in Najaf/Iraq case study: Al Shelan Khan <i>N.K.S. AL-Saoudi & M.Sh. AL-Shakerchy</i>	123
Seismic vulnerability reduction for historical buildings: The case study of house of mosaics <i>L. Alterio, L. Evangelista, G. Russo & F. Silvestri</i>	129
New evidences on the Phlegraean bradyseism in the area of <i>Puteolis</i> harbour <i>L. Amato & C. Gialanella</i>	137
Important works in the town centre and preservation of existing heritage: The Grand Carré Jaude in Clermont-Ferrand (France) <i>F. Ambrosini, P. Berthelot, F. Durand & A. Reynaud</i>	145
Drilled spiral piles in St. John's Church of Tartu, Estonia <i>K. Avellan</i>	149
Settlement induced by TBM excavation under the Vittoria's Church in Napoli <i>S. Aversa, E. Bilotta, G. Russo & A. di Luccio</i>	157

Ground improving injections underneath historical buildings: Five case histories as an overview of a technique <i>V. Berengo</i>	165
Monitoring of the temperature-moisture regime of rock dwellings in Brhlavce village (Slovakia) <i>V. Boháč, D. Fidiriková, V. Vretenár, T. Durmeková, I. Šimková, V. Greif & J. Vlčko</i>	175
Restoration projects and remedial works in the historical island of Ventotene <i>N. Bosco, P. Croce, B. Palma, D. Pingitore & M. Ramondini</i>	183
19th and 20th century coastal military installations affected by coastal erosion in the UK <i>E.N. Bromhead, M-L. Ibsen & D. Tapete</i>	191
Interpretation and modelling of the subsidence at the archaeological site of Sybaris (Southern Italy) <i>F. Cafaro, F. Cotecchia, V. Lenti & R. Pagliarulo</i>	199
Geotechnical aspects in the preservation of the <i>Domus Tiberiana</i> in Rome <i>G. Calabresi, L. Cavalera, V. Ascoli Marchetti & M.G. Filetici</i>	207
New underground lines in historic centres: Experiences in Naples <i>E. Campa, A.M. Ajmone Cat, C. Fioretti & L. Mormone</i>	215
The Benedictine Basilica of S. Angelo in Formis (Southern Italy): A therapy without diagnosis? <i>A. Cammarota, G. Russo, C. Viggiani & M. Candela</i>	225
The vineyard of the monastery of S. Martino in Napoli <i>M. Candela, C. Viggiani & R. Viparelli</i>	233
Site characterization by in situ and laboratory tests for the structural & architectural restoration of Saint Nicholas Church, Nicosia, Cyprus <i>A. Cavallaro, L. Cessari & E. Gigliarelli</i>	241
Long-term mechanical behavior of wooden pile foundation in Venice <i>F. Ceccato, P. Simonini & A. Lionello</i>	249
Cultural Heritage and physical environment: A geo-archaeological approach to the analysis of interaction and risk factors <i>A. Cinti, L. Coppola & E.N. Bromhead</i>	257
Settlement response of masonry constructions <i>M. Como</i>	265
Assessment of geological and geotechnical conditions for rebuilding Avala's television tower <i>S. Ćorić, D. Rakić, G. Hadži-Niković, T. Janković, V. Filipović & B. Marjanović</i>	273
Afghanistan, Buddhas of Bamiyan: Emergency consolidation of the cliffs and niches <i>C. Crippa, R. Granata & C. Margottini</i>	279
Archaeology and geotechnical engineering <i>S. D'Agostino & G. Tocco</i>	289
Long-term stability of old cathedrals in St. Petersburg <i>R.E. Dashko & A.V. Shidlovskaya</i>	299
A study for the requalification and safety against natural hazards of the environmental and building heritage of Sant'Agata de' Goti (Italy) <i>F. de Silva, M. Melillo, D. Calcaterra, F. Fascia, A. Scotto di Santolo, F. Silvestri & L. Stendardo</i>	307
Study and monitoring for conservation of Sanctuary of Santa Maria Assunta at Monteortone (Abano Terme, Padova) <i>A. Dei Svaldi & A. Mazzucato</i>	317
Slope dynamics, monitoring and geological conservation of the Siq of Petra (Jordan) <i>G. Delmonaco, C. Margottini & D. Spizzichino</i>	325

Historic and non-historic building impact assessment methodology for major tunnelling infrastructure projects <i>M. Devriendt, E. Palmer, R. Hill & D. Lazarus</i>	335
Dynamic identification and seismic behaviour of the Ghirlandina tower in Modena (Italy) <i>A. Di Tommaso, R. Lancellotta, D. Sabia, D. Costanzo, F. Focacci & F. Romaro</i>	343
Performance evaluation of bending strength to predict durability of ornamental gneiss from Santo Antônio de Pádua, RJ, BR <i>J.L.E. Dias Filho, P.C.A. Maia, G.C. Xavier & P.A.M. Fernandes</i>	353
The role of the geotechnical engineer in archaeological work: The Greek experience <i>D. Egglezos, D. Moullou & M. Ioannidou</i>	359
Re-burial of the Arrephorion on the Athenian Acropolis: An in situ rescue intervention against degradation <i>D.N. Egglezos</i>	367
Egyptian experience in the preservation of monuments and historic structures. A case study: Hibis Temple, El-Kharga—Egypt <i>M.K. El-Ghamrawy, M.A. Sakr & S.A. Gad</i>	377
Diagnostic of the colonial structure “Palacio del Segundo Cabo” in Havana, Cuba <i>S. Figueredo, Y. Gámez, R. Lorenzo, J. de la Rosa & R.P. da Cunha</i>	385
Softening and swelling mechanism affecting south slope of Civita di Bagnoregio (VT) <i>F. Garbin, C. Margottini, R. Brancaloni & A. Sonnessa</i>	395
Evaluation of the soil disturbance due to the installation of prefabricated vertical drains: An analytical approach applied to case histories <i>A. Ghandeharioon</i>	403
Preservation and monitoring of the Frari bell tower in Venice <i>G. Gottardi, M. Marchi, A. Lionello & P.P. Rossi</i>	411
Collapse of a backfilled wall at the Castle Wespenstein <i>I. Herle, J. Männer, E. Schwiteilo & J. Wehr</i>	425
Geotechnical problems on historical buildings from Transylvania <i>N.M. Ilieş & A. Popa</i>	431
Research and advanced technology in the restoration of the monuments of the Athenian Acropolis <i>M. Ioannidou</i>	437
Estimation of moisture condition with salinity in the ground behind the Dunhuang Mogao Grottoes using the electrical resistivity method <i>M. Ito, K. Koizumi, K. Oda, T. Miyawaki, C. Piao, C. Tanimoto, Y. Iwasaki, X. Wang, Q. Guo & S. Yang</i>	447
Dismantling for reconstitution of N1 Tower of Prasat Suor Prat, Angkor Thom, Cambodia <i>Y. Iwasaki, Y. Akazawa, M. Fukuda, J. Nakazawa, K. Nakagawa, I. Shimoda & T. Nakagawa</i>	455
A variegated embankment dam in a historical territory <i>R. Jappelli</i>	465
Safety and/or security of monuments? An apparent dilemma <i>R. Jappelli</i>	473
Strong motion record processing for the Athenian Acropolis seismic response assessment <i>I.S. Kalogeras & D. Egglezos</i>	483
Settlements due to tail gap of shield tunnelling <i>D. Kolymbas</i>	493
An innovative approach for reducing the seismic risk of existing buildings and historic sites <i>D. Lombardi, A. Flora, S. Lirer & F. Silvestri</i>	507

Preservation of historic structures and monuments using minimally invasive Screw-Piles and Helical Anchors—two cases <i>A.J. Luteneegger, D. Robson & P. Mohan</i>	515
Seismic risk assessment of San Gimignano towers: Geotechnical aspects and soil-structure interaction <i>C. Madiati, S. Renzi & G. Vannucchi</i>	523
Analytical modelling of the creep-rotation rate for leaning towers <i>M. Marchi, I. Fabbri, G. Gottardi, R. Butterfield & R. Lancellotta</i>	531
Geotechnical and geophysical characterization of Moai statues—Rapa Nui Easter Island (Chile) <i>C. Margottini, D. Spizzichino, L. Orlando, M. Marsella, B. Renzi, A. Sonnessa, O. Pandolfi & P. Soddu</i>	539
Landslide risk and monitoring system for conservation of Vardzia monastery, Georgia <i>C. Margottini, D. Spizzichino & A. Sonnessa</i>	549
Strength and structure of the roofed mud-walls of Toji Temple <i>M. Mimura, M. Yoshimura & T. Terao</i>	559
Spatial-temporal analysis of the subsidence in the city of Bologna <i>G. Modoni, G. Darini, R.L. Spacagna, M. Saroli, G. Russo & P. Croce</i>	565
Repair works at Saint Claire Convent in Chinchón (Madrid, Spain) <i>P.R. Monteverde & J.M. Avila-Jalvo</i>	573
Groundwater management during excavations of S. Pasquale station in Naples <i>L. Mormone, G. Falconio & A. Mandolini</i>	579
Offshore soil investigations on the bottom of Ohrid Lake and authentic reconstruction of timber piles settlement <i>D. Nikolovski, B. Veljanovski & A. Stojkovska</i>	589
Groundwater development and management in Siem Reap, Cambodia: Impacts of groundwater pumping on Angkor Wat <i>M. Nishigaki, S. Takahashi, M. Takahashi & Y. Maruo</i>	595
Unsaturated sand in the stability of the cuesta of the Temple of Hera (Agrigento) <i>N. Nocilla, L. Ercoli, M. Zimbardo, A. Nocilla, P. Meli, G. Grado, G. Parello & G. Presti</i>	603
Slope consolidation of Monteagudo de las Vicarias castle (Soria) <i>C.S. Oteo & P. de la Fuente</i>	613
Load transfer in micropile underpinning of old foundations <i>J.M. Rodríguez Ortiz</i>	621
Construction of the Line C San Giovanni station in Rome <i>E. Romani & N. Miniero</i>	627
Permanence and preservation of the Metztitlán convent in Hidalgo, Mexico <i>E. Santoyo-Villa & E. Ovando-Shelley</i>	633
The Fontanelle Cemetery: Between legend and reality <i>A. Scotto di Santolo, L. Evangelista & A. Evangelista</i>	641
A class C prediction of the settlements induced in a historical masonry structure by the excavation of shallow twin tunnels <i>M. Sebastianelli, G. de Felice, M. Malena, A. Amorosi, D. Boldini & G. Di Mucci</i>	649
Soil structure interaction on the dynamic behavior of two historic masonry structures <i>S. Sica, F. Ceroni & M.R. Pecce</i>	657
New Lanark Walls: Examples of sustainable design for a World Heritage Site <i>M.J. Smith</i>	669

Evaluating the effects of tunnel construction on monuments: The example of the Basilica di Massenzio in Rome <i>F.M. Soccodato, L. Callisto, S. Rampello & G.M.B. Viggiani</i>	675
The preservation of the historical, archeological and artistic heritage of Orvieto: An interdisciplinary project <i>F.M. Soccodato, E. Martini, L. Tortoioli & A.M. Mazzi</i>	683
Landslide risk assessment and management in the archaeological site of Machu Picchu (Peru) <i>D. Spizzichino, C. Margottini & L.M. Puzzilli</i>	697
The rebuilding of San Piero a Grado bell tower <i>N. Squeglia</i>	709
Safeguard stories of living monuments (unstable towns of the region of Umbria) <i>P. Tamburi & E. Martini</i>	717
Geohazards and climate change issues for the preservation of the Saxon Shore in South Britain <i>D. Tapete & E.N. Bromhead</i>	725
Preservation and reconstruction of historic monuments in Saint Petersburg with provisions for soil-structure interaction <i>V.M. Ulitsky, A.G. Shashkin, K.G. Shashkin & M.B. Lisyuk</i>	735
Localized settlements of an ancient hospital foundation: Analysis of the problem to assess a possible reinforcement intervention <i>R. Valentino, E. Coïsson, F. Freddi & F. Ottoni</i>	743
Geotechnical investigation and stabilization of the foundations of a World Heritage in Portugal, the Guimarães Castle <i>A. Viana da Fonseca, A. Arêde, E. Paupério & A. Costa</i>	751
Safeguarding interventions for two historical sites in the Middle East <i>B. Vingiani & G. Salerno</i>	761
Use of jet grouting technique to realize substructures of historic buildings: The example of an apartment building in Warsaw <i>K. Wanik</i>	769
Geotechnical and structural investigations of historical monuments of Kazakhstan <i>A. Zh. Zhussupbekov, T.O. Zhunisov, A.Z. Issina & T. Awwad</i>	779
The safety of an industrial archaeological heritage: The underground quarries in Marsala (Sicily) <i>M. Zimbardo, L. Ercoli, C. Cannone & A. Nocilla</i>	785
Author index	793